



Buy this item and view more at www.ironplanet.com or call 800-211-3983

Item #13355288 - 2019 Rubble Master SC5700M Screen



Item Details:

- Features: Tier 4, Cummins QSL 6 Cylinder 97 kW 3.8 L Diesel Engine, Requires Diesel Exhaust Fluid, 3660 mm x 1525 mm Double Deck Screen, 32 in Wide Feed Conveyor, 46 in Wide Under Screen Conveyor, 25 in Wide Left Discharge Conveyor, 25 in Wide Right Discharge Conveyor, 46 in Wide End Discharge Conveyor, Cable Remote Control, 16 in Triple Grouser Track Shoes
- Meter Reading: 2,298 Hours
- Serial # : MSC5700M-2D-13-04
- Inspection Completed: 5/5/25

Shipping Details:

- Location Tennessee (Nashville area)
- Loading Dock Available: No
- Pickup Hours: -
- You will need a copy of your IronPlanet Item Release to pick the item up. Please call one day in advance to schedule pickup.

Inspection Report

Note: This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.

Inspection Ratings Key	
★★★★	Limited use or recently replaced. Free of visible wear or defects.
★★★☆☆	Performs within the tolerances expected for age and type of item
★★☆☆☆	Although performing, shows indication of needing repair or replacement
★☆☆☆☆	Needs immediate repair/replacement. Requires work if it is to perform as expected

Control Station

Pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.


Item	Assessment	Photo
Control Station #6		
Gauges	Operational	
Engine Controls	★★★★☆	
Crusher/Screen Controls	★★★★☆	
Limited Function Check	The main components are in place and operational as noted.	
Control Station #1		

Control Station #2		
--------------------	--	---

General Appearance		
Item	Assessment	Photo
Picture, Left Front Corner		
Picture, Left Rear Corner		
Picture, Right Rear Corner		
Picture, Right Front Corner		
Serial Number / VIN	MSC5700M-2D-13-04	
Hour Meter / Odometer	2298 hrs	


v3 General Appearance # 1		
v3 General Appearance # 2		
v3 General Appearance # 3		
v3 General Appearance # 4		
v3 General Appearance # 5		
v3 General Appearance # 6		
v3 General Appearance # 7		



v3 General Appearance # 8		
v3 General Appearance # 9		
v3 General Appearance # 10		
v3 General Appearance # 11		
v3 General Appearance # 12		
v3 General Appearance # 13		
v3 General Appearance # 14		

v3 General Appearance # 15		
v3 General Appearance # 16		
v3 General Appearance # 17		
v3 General Appearance # 18		
v3 General Appearance # 19		
v3 General Appearance # 20		
v3 General Appearance # 21		

v3 General Appearance # 22



Engine		
Item	Assessment	Photo
Emission Certification Label	None found	
Starter	Operational	
Exhaust System		
Radiator	★★★★☆	
Oil Leaks	No dripping leaks	
Fuel Leaks	No dripping leaks	
Cooling System Leaks	No dripping leaks	
Engine - Left Side		

Engine - Right Side		
DEF / AdBlue Tank		
Limited Function Check (Engine)	After jump starting, the engine ran.	
Engine #1		
Engine #2		
Engine #3		

Hydraulics		
See photos for condition		
Item	Assessment	Photo
Pumps (Hydraulics)	★★★★☆	
Hydraulic Motors	★★★★☆	
Valves	★★★★☆	
Hydraulic Tank	★★★★☆	
Hoses		
Conveyor Cylinders	★★★★☆	

Power Travel Drive System	★★★★☆ Travels properly	
Limited Function Check	The hydraulic system was operational.	
Hydraulics #1		
Hydraulics #2		
Hydraulics #3		
Hydraulics #4		
Hydraulics #5		
Hydraulics #6		

Hydraulics #7		
Hydraulics #8		
Hydraulics #9		
Hydraulics #10		
Hydraulics #11		
Hydraulics #12		
Hydraulics #13		

Hydraulics #14		
Hydraulics #15		

Chassis		
Item	Assessment	Photo
Discharge Conveyor Condition	★★★★☆	
Discharge Conveyor Drive Motor	★★★★☆ Not operationally checked	
Discharge Conveyor Rollers	★★★★☆	
Discharge Conveyor Head and Tail Pulley	★★★★☆	
Screen Deck	★★★★☆ Number of decks: 2	
Chassis #1		


Chassis #2		
Chassis #3		
Chassis #4		
Chassis #5		
Chassis #6		
Chassis #7		
Chassis #8		

Chassis #9



Undercarriage		
Item	Assessment	Photo
Left Roller Frame		
Left Track Tensioner		
Left Track Pads		
Left Grouser Height	16 mm	
Left Track Links		
Left Track Bushings	Bushings have not been turned	

Left Carrier Rollers		
Left Track Rollers		
Left Idler		
Left Sprocket		
Right Roller Frame		
Right Track Tensioner		
Right Track Pads		

Right Grouser Height	16 mm	
Right Track Links		
Right Track Bushings	Bushings have not been turned	
Right Carrier Rollers		
Right Track Rollers		
Right Idler		
Right Sprocket		

Undercarriage #1		
Undercarriage #2		

Buy this item and view more at www.ironplanet.com or call 800-211-3983
IronPlanet , Inc. © 2012 All Rights Reserved